Box 153 Jul-Aug 1888 Mint of the United States at Philadelphia, Pa., August 14, 1888. In regard to a letter from the Usrayer in Charge at Denver Colo, complaining of a discrepancy in fineness of bullion shipped from that Office; I will state that the melt in question was composed of a number of small bars, and it arrayed as follows 785.9. 785.8. 785.9. Having made a calculation of what the Fineness should have been, I have that there was a discrepancy, and accombing made re-anays, totalen new tamples, but with the same result. Not satisfied with this result, I had the bullion remelted and arrayed, with the timeres as reported. The number of the Philadelphia

## Box 153 Jul-Aug 1888

Mint of the United States at Philadelphia, Ha.,
ASSAY DEPARTMENT,

188

Memorandum is 123 - Mot 181 as Hated in the letter.

The Assayer at the Denver mint will have to look for the discrepancy at his institution, as we made every effort to arrive at an agreement in fineness

Very Respectfully Jacob B. Eckfelett Amayer

Hon. Daniel M. Fox Superintendent Mint of the United States at Philadelphia, Pa., Assay Department, August 14, 1888

Sir

In regard to a letter from the Assayer in charge at Denver Colo. complaining of a discrepancy in fineness of bullion shipped from that office; I will state that the Melt in question was composed of a number of small bars, and it assayed as follows 785.9, 785.8, 785.9. Having made a calculation of what the fineness should have been, I saw that there was a discrepancy, and accordingly made re-assays, from new samples, but with the same result. Not satisfied with this result, I had the bullion re-melted and assayed, with the fineness as reported.

The number of the Philadelphia Memorandum is 123 – not 181 as stated in the letter.

The Assayer at the Denver mint will have to look for the discrepancy at his institution, as we made every effort to arrive at an agreement in fineness.

Very Respectfully, Jacob B. Eckfeldt Assayer

Hon. Daniel M. Fox Superintendent